

ecology and environment, inc.

160 SPEAR STREET, SAN FRANCISCO, CALIFORNIA 94105, TEL. 415/777-2811

2752

International Specialists in the Environment

MBMORANDUM

TO:	Lisa Nelson, EPA Region IX					
FROM:	Karen Ladd, Ecology and Environment, Inc.					
DATE:	July 12, 1991					
SUBJECT:	Completed Work					
cc:	Marcia Brooks, E & E FIT					
Attached is the following completed:						
PA	PA Review_X SSI LSI SIRe					
Other						
Site Name:	Jaquays Equipment Company					
EPA ID #:	AZD009017989 (3807)					
City, County	: Phoenix, Maricopa County					
State Recommendation: No Further Action Recommended (for Reviews only)						
(101 Keviews	only)					
	FOR EPA USE ONLY					
CERCLIS Lead:	: PA complete reconnecd: NFRAD					
	Ron She lead					

cac/jaquays/cwm-trans

(275=)

PRELIMINARY ASSESSMENT REVIEW

SUBMITTED TO:

Lisa Nelson, EPA Region IX Site Assessment Manager

PREPARED BY:

Cathleen Cauz, Ecology and Environment, Inc.

DATE:

July 12, 1991

SITE:

Jaquays Equipment Company, prepared by Ana I. Vargas

of Arizona Department of Environmental Quality,

dated June 10, 1991

TDD#:

F9-9103-020

BPA ID#:

AZD009017989

FIT REVIEW/CONCURRENCE:

Janet C Kaps 7/12/91

cc: FIT Master File

INTRODUCTION

This Preliminary Assessment has been reviewed by Ecology and Environment, Inc.'s Field Investigation Team (E & E FIT) according to U.S. Environmental Protection Agency (EPA) guidelines presented in the "Preliminary Assessment Interim Guidance Document for Fiscal Year 1988." FIT has evaluated this site with respect to the Hazard Ranking System (HRS) (Federal Register, Vol. 55, No. 421, 51532-51667, December 14, 1990).

RCRA STATUS

Generator	Small Quantity Generator	Transporter
TSD	X Not Listed in RCRA Database	

HRS CONSIDERATIONS

- o While groundwater is a supply of drinking water in Phoenix, it is largely supplemented by imported surface water;
- No known beneficial uses of surface water downgradient of the site; and

o No sources of hazardous substances available to air exist on site.

COMMENTS

The report was generally well written and complete. Information regarding the surface of the site (concrete, asphalt, bare soil, etc.) is important in the evaluation of the soil exposure pathway and should be included in the soil exposure section.

Under the Hazard Ranking System, information regarding the amount each drinking water well contributes (in percent) to the total system is necessary. Thus for the Jaquays Equipment Company site, each of the 87 City of Phoenix groundwater wells supplies drinking water to one eighty-seventh of 17 percent of the population. A breakdown of drinking water wells within each target distance limit is also necessary information for an accurate assessment of the groundwater target population.

CONCLUSIONS		
Potentially eligible for National Priorities	List	
X Appears to be ineligible for National Prioris	ies List	
STATE RECOMMENDATION		
X No Further Remedial Action Planned under CERC	CLA	
Medium-priority Screening Site Inspection (mS	SSI)	
High-priority Screening Site Inspection (hSSI	:)	
EPA RECOMMENDATION		
No Further Remedial Action Planned under CERCLA	Initial LO	<u>Date</u> <u>819-9</u>
Higher-Priority SSI under CERCLA		
Lower-Priority SSI under CERCLA		
Defer to Other Authority (e.g., RCRA, TSCA, NRC)		
Notes:		